

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program

Supervisor DRH

Report Date February 8, 2006

Mine Name: Desert Sienna	Permit numbe (unpermitted)	er: S/015/09)3
Operator Name: Bown Stone Products	Inspection Da Time: About	•	
Inspector(s): Paul Baker Other Participants: Rebecca Doolittle, Price BLM Mine Status: Unpermitted	Weather: Cle	ear, 30's, a li	ttle snow on
Elements of Inspection	Evaluated	Comment	Enforcemen
 Permits, Revisions, Transfer, Bonds Public Safety (shafts, adits, trash, signs, highwalls) Protection of Drainages / Erosion Control Deleterious Material Roads (maintenance, surfacing, dust control, safety) Concurrent Reclamation Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes) Water Impoundments Soils Revegetation Air Quality Other 			
Purpose of Inspection: We wanted to see where this site is and to see what the conditions are like.			

Inspection Summary:

1. Permits, Revisions, Transfer, Bonds

The Division originally received a Notice of Intention to Commence Small Mining Operations on December 1, 2005, but did not receive the permit fee. By letter dated December 2, 2005, the Division notified the operator of the need to submit the permit fee, and the fee was received January 13, 2006. Revised information sent to the BLM December 15, 2005, was received from them on January 18, 2006, by Fax transmission. During this inspection, Ms. Doolittle gave me a color copy of the map.

12. Other

This site is located at the Molen Seep east of Ferron, an area I had not previously visited in over a hundred trips to Emery county. The "seep" is a small canyon (Photos 1 and 4) with a sandstone rim. Surrounding areas are relatively flat with a little soil over the sandstone bedrock. There is a pinyon/juniper vegetation community on the plateau, but the trees are widely spaced (Photo 2).

There is an existing road to within a few hundred yards of the edge of the canyon, and there is something of a two-track road that winds through the trees to near the canyon (see the attached map). This two track road will need to be included as part of the disturbed area. The operator intends to

Inspection Date: January 20, 2006; Report Date: February 8, 2006

Page 2 of 2 S/015/083

make some modifications to the existing east-west road, and these modifications will also need to be part of the disturbed area.

Ms. Doolittle explained that the area has been designated by the BLM as an Area of Critical Environmental Concern, primarily because of Native American rock art and because of the possibility of finding vertebrate fossils in the sandstone.

The operator plans to begin mining at the edge of the canyon and work back away from the canyon. The stone would be used as flagstone.

Conclusions and Recommendations:

I anticipate there will be little soil to salvage but that there will be a fair amount of waste rock. The operator will need to handle the waste in a way that it can be used as a substitute soil.

Inspector's Signature

Directions to Site:

Beginning on Main Street in Ferron, head east on the first street south of Ferron Creek for about 3 miles, proceed south for just over a mile, then go southeast for about one and one-half miles. At this point, there is an intersection with a corral. Take the right fork south for about two miles, then there is a road heading basically east through the shale. Follow this road for about one-half mile, and there is something of a two-track (indistinct) leading south toward Molen Seep. This is the general area where the operator plans to mine.

PBB:pb

cc:

Jerome Bown, Operator Rebecca Doolittle, Price BLM

Attachment: GPS & Photos

P:\GROUPS\MINERALS\WP\M015-Emery\S150093-DesertSienna\final\ins-01202006.doc

ATTACHMENT

Photographs

S/015/083, Desert Sienna Mine, Bown Stone Products

Inspection Dated: January 20, 2006; Report Dated: February 8, 2006




Photo 1. Molen Seep. We did not look closely at the channel, but based on the nature of the channel, I suspect it has flowing water much of the year.




Photo 2. The plateau above the canyon.



Photo 3. Rimrock at the edge of the canyon.





Photo 4. Another view of the edge of the canyon.



ownship 21 S Range 08 E Section 06 SLBM Mine Name: Desert Sienna Mine Number: S0150093

Inspection Date Jan. 20, 2006 Map Produced by DKS

Acres Disturbed Acres Regraded Acres Seeded Road Acres Disturbed 0000

Total Acres Distrubed 0

Acres Released
Acres Excluded
Acres PreExisting
Acres Prelaw 0000


Legend
All items symbolized in legend may not be appear on map

*** Township or range line: location doubtful Township or range Line

== Main Dirt Road Interchange Primary Route US Route State Route

DOQ imagery date 2004

--- Trail



Dept. of Natural Resources
Division of Oil, Gas, and Mining
Mineral Mines Program

Different data sources and input scales may cause misalignment of data layers. This product may not meet DOGM standards for accuracy and content.

Verify Scale